

APRILIA BALANCE SHAFT TIMING

IF YOU HAVE TO STRIP THE BOTTOM END OF YOUR ENGINE, IT IS VITAL THAT THE BALANCE SHAFT IS TIMED CORRECTLY. INCORRECT TIMING OF THE BALANCE SHAFT WILL RESULT IN EXCESSIVE VIBRATION, WHICH IN EXTREME CASES CAN CAUSE THE PISTON RING PEGS TO LOOSEN AND ALLOW THE RING TO ROTATE AND DAMAGE THE CYLINDER.

